WATER SYSTEM ID NUMBER	SYSTEM SPECIFIC ID	SERVICE ADDRESS	WATER MAIN MATERIAL	CONNECTOR OR GOOSENECK MATERIAL	WAS LEAD EVER UPSTREAM OF THIS SERVICE?	PWS-OWNED SERVICE LINE MATERIAL	WAS PWS-OWNED SERVICE LINE EVER LEAD?	1"	YEAR PWS-OWNED SERVICE LINE INSTALL DATE	PRIVATE SIDE SERVICE LINE MATERIAL	PRIVATE SIDE SERVICE LINE SIZE	PRIVATE SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	STRUCTURE - PRIMARY PLUMBING MATERIAL 1	STRUCTURE SECONDARY PLUMBING MATERIAL 2	YEAR (RANGE) STRUCTURE PLUMBING MATERIAL INSTALLED	THIS LOCATION WILL BE USED FOR LEAD AND COPPER SAMPLE SITE PLAN?	REPLACE GOOSENECK/PIGTAIL CONNECTOR	LSL CATEGORY IN INVENTORY	SAMPLE SITE SELECTION CRITERIA (SITE TIER)	Would this count as full LSLR if Lead is removed?	REQUIRES RESIDENT NOTIFICATION IF LSL DISTURBED	REQUIRES RISK MITIGATION (POU OR PITCHER FILTER)	SOURCE OF INFORMATION USED SERVICE LINE IDENTIFICATION
																			Yes	Lead	Tier 5	Yes	Yes	Yes	
15		306 E 8th								Copper	3/4"	1996	Other	No	PVC	Copper	Between 1989 and 2014		Yes	Lead	Tier 5	Yes	Yes	Yes	
20		301 E 8th								Unknown	Unknown	us property owner re	Single Family	No	PVC	Unknown	Unknown		Yes	Lead	Tier 5	Yes	Yes	Yes	
22		777 Main								Unknown	Unknown	us property owner re	Other	No	PVC	Unknown	Unknown		Yes	Lead	Tier 5	Yes	Yes	Yes	
24		769 Main								Copper	3/4"	t to be original to cor	Single Family	Yes	Copper		Before 1989		Yes	Lead	Tier 1	Yes	Yes	Yes	
25		759 Main								Unknown	Unknown	t to be original to cor	Single Family	No	Unknown	Unknown	Before 1989		Yes	Lead	Tier 1	Yes	Yes	Yes	
26		755 Main								Unknown	Unknown	unknown		Unknown	Unknown	Unknown	Unknown		Yes	Lead	Tier 5	Yes	Yes	Yes	
27		751 Main								Unknown	Unknown	ed to be original cons	Other	No	Unknown	Unknown	Unknown		Yes	Lead	Tier 5	Yes	Yes	Yes	
28		752 Main								Copper	Unknown	unknown	Other	No	Unknown	Unknown	Before 1989		Yes	Lead	Tier 5	Yes	Yes	Yes	
29		760 Main								Lead	Unknown	ed to be original cons	Other	No	Copper	PEX	Before 1989		Yes	Lead	Tier 5	Yes	Yes	Yes	
30		758 Main								Unknown	Unknown	us property owner re	Single Family	No	PVC	Unknown	Before 1989		Yes	Lead	Tier 1	Yes	Yes	Yes	
31		766 Main								Galvanized Steel	Unknown	nt property owner re	Other	No	PEX	PVC	Unknown		Yes	Lead	Tier 5	Yes	Yes	Yes	
33		768 Main								Lead	Unknown	unknown	Other	No	Unknown	Unknown	Before 1989		Yes	Lead	Tier 5	Yes	Yes	Yes	
40		808 Main								Unknown	Unknown	t to be original to cor	Other	No	Unknown	Unknown	Unknown		Yes	Lead	Tier 5	Yes	Yes	Yes	
44		900 Main								Unknown	Unknown	unknown		Unknown	Unknown	Unknown	Unknown		Yes	Lead	Tier 5	Yes	Yes	Yes	
45		904 Main								Unknown	Unknown	unknown	Other	Unknown	Unknown	Unknown	Unknown		Yes	Lead	Tier 5	Yes	Yes	Yes	
46		906 Main								Unknown	Unknown	unknown	Other	Unknown	Unknown	Unknown	Unknown		Yes	Lead	Tier 5	Yes	Yes	Yes	
47		922 Main								Unknown	Unknown	ed to be original cons	Other	No	PVC	Unknown	Before 1989		Yes	Lead	Tier 5	Yes	Yes	Yes	
48		926 Main								Lead	Unknown	t to be original to cor	Other	No	Copper	PVC	Unknown		Yes	Lead	Tier 5	Yes	Yes	Yes	
49		1014 Main								Copper	3/4"	t to be original to cor	Other	Yes	PEX	Copper	Copper	After 2014	Yes	Lead	Tier 5	Yes	Yes	Yes	
50		1004 Main								Unknown	Unknown	t to be original to cor	Other	No	Unknown	Unknown	Unknown		Yes	Lead	Tier 5	Yes	Yes	Yes	
51		902 Main								Unknown	Unknown	ed to be original cons	Other	No	Unknown	Unknown	Before 1989		Yes	Lead	Tier 5	Yes	Yes	Yes	
52		822 Main								Copper	3/4"	t to be original to cor	Other	No	PVC	PVC	Before 1989		Yes	Lead	Tier 5	Yes	Yes	Yes	
55		816 Main								PVC	1"	2000	Other	No	Copper Pipe with Lead Solder	PEX	Between 1989 and 2014		Yes	Lead	Tier 5	Yes	Yes	Yes	
56		1102 Main								Unknown	Unknown	ed to be original cons	Single Family	No	PVC	PEX	Before 1989		Yes	Lead	Tier 1	Yes	Yes	Yes	
58		805 Main								Unknown	Unknown	ed to be original cons	Other	No	Unknown	Unknown	Before 1989		Yes	Lead	Tier 5	Yes	Yes	Yes	
60		815 Main								PEX	3/4"	unknown	Single Family	No	PEX	PVC	Unknown		Yes	Lead	Tier 1	Yes	Yes	Yes	
61		817 Main								Unknown	Unknown	unknown		Unknown	Unknown	Unknown	Unknown		Yes	Lead	Tier 5	Yes	Yes	Yes	
62		901 Main								Unknown	Unknown	ed to be original cons	Other	No	Copper	Unknown	Before 1989		Yes	Lead	Tier 5	Yes	Yes	Yes	
63		911 Main								Unknown	3/4"	ed to be original cons	Other	No	Copper	Copper	Before 1989		Yes	Lead	Tier 5	Yes	Yes	Yes	
69		927 Main								Unknown	Unknown	ed to be original cons	Other	Yes	PVC	PVC	After 2014		Yes	Lead	Tier 5	Yes	Yes	Yes	
70		1001 Main								Unknown	Unknown	unknown		Unknown	Unknown	Unknown	Unknown		Yes	Lead	Tier 5	Yes	Yes	Yes	
72		1003 Main								Unknown	Unknown	unknown	Single Family	No	Unknown	Unknown	Unknown		Yes	Lead	Tier 1	Yes	Yes	Yes	
74		1021 Main								Unknown	Unknown	ed to be original cons	Other	No	Unknown	Unknown	Unknown		Yes	Lead	Tier 5	Yes	Yes	Yes	
0074-1		1021 Main								Unknown	Unknown	ed to be original cons	Other	No	Unknown	Unknown	Unknown		Yes	Lead	Tier 5	Yes	Yes	Yes	
75		705 Main - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
77		619 Main - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
84		110 W 6th								Unknown	Unknown	unknown			Unknown	Unknown	Unknown		Yes	Lead	Tier 5	Yes	Yes	Yes	
86		603 Sycamore								Unknown	Unknown	unknown		Unknown	Unknown	Unknown	Unknown		Yes	Lead	Tier 5	Yes	Yes	Yes	
88		210 W 6th								Unknown	Unknown	unknown		Unknown	Unknown	Unknown	Unknown		Yes	Lead	Tier 5	Yes	Yes	Yes	
89		611 Cedar - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
90		314 W 6th - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
91		601 Cedar - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
92		555 Cedar - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
93		211 W 6th								Unknown	Unknown	ed to be original cons	Single Family	No	PVC	Unknown	After 2014		Yes	Lead	Tier 1	Yes	Yes	Yes	
94		209 W 6th								Unknown	Unknown	unknown		Unknown	Unknown	Unknown	Unknown		Yes	Lead	Tier 5	Yes	Yes	Yes	
95		207 W 6th								Unknown	Unknown	unknown		Unknown	Unknown	Unknown	Unknown		Yes	Lead	Tier 5	Yes	Yes	Yes	
96		203 W 6th								Unknown	Unknown	unknown		Unknown	Unknown	Unknown	Unknown		Yes	Lead	Tier 5	Yes	Yes	Yes	
98		109 W 6th								Unknown	Unknown	nt property owner re	Single Family	No	Unknown	Unknown	Unknown		Yes	Lead	Tier 1	Yes	Yes	Yes	
99		105 W 6th								Unknown	Unknown	unknown	Single Family	Unknown	Unknown	Unknown	Unknown		Yes	Lead	Tier 1	Yes	Yes	Yes	
100		101 W 6th								Unknown	Unknown	unknown	Single Family	Yes	Copper	PVC	Unknown		Yes	Lead	Tier 1	Yes	Yes	Yes	
101		510 Laurel								Copper	3/4"	ed to be original cons	Single Family	Yes	PVC	PEX	Between 1989 and 2014		Yes	Lead	Tier 1	Yes	Yes	Yes	
102		103 E 6th								Unknown	Unknown	unknown		Unknown	Unknown	Unknown	Unknown		Yes	Lead	Tier 5	Yes	Yes	Yes	
104		521 Main - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
105		515 Main - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
107		501 Linn - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
108		409 Laurel								PVC	Unknown	nt property owner re	Single Family	No	PVC	PVC	Between 1989 and 2014		Yes	Lead	Tier 1	Yes	Yes	Yes	
109		107 W 5th								Unknown	Unknown	ed to be original cons	Single Family	No	Unknown	Unknown	Unknown		Yes	Lead	Tier 1	Yes	Yes	Yes	
110		104 W 5th								PEX	3/4"	unknown	Single Family	No	Copper	Galvanized Steel	Before 1989		Yes	Lead	Tier 1	Yes	Yes	Yes	
111		110 W 5th - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
113		501 Laurel - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
115		553 Cedar								Galvanized Steel	1/2"	ed to be original cons	Single Family	No	PVC	PEX	Unknown		Yes	Lead	Tier 1	Yes	Yes	Yes	
117		207 W 5th - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
119		111 W 5th								Galvanized Steel	3/4"	ed to be original cons	Single Family	Yes	PVC	Unknown	Unknown		Yes	Lead	Tier 1	Yes	Yes	Yes	
120		405 Sycamore - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
122		210 W 4th - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
124		109 W 4th - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
125		205 W 4th								Galvanized Steel	Unknown	ed to be original cons	Single Family	No	Copper	Galvanized Steel	Before 1989		Yes	Lead	Tier 1	Yes	Yes	Yes	
126		360 Cedar - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
127		209 W 4th - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
128		361 Cedar								Unknown	Unknown	unknown	Single Family	No	Unknown	Unknown	Unknown		Yes	Lead	Tier 1	Yes	Yes	Yes	
129		355 Cedar								Galvanized Steel	3/4"	ed to be original cons	Single Family	No	Copper	Galvanized Steel	After 2014		Yes	Lead	Tier 1	Yes	Yes	Yes	
131		301 W Miami - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
132		320 Cedar - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
134		321 Sycamore								Copper	Unknown	ed to be original cons	Single Family	No	Copper	Unknown	Unknown		Yes	Lead	Tier 1	Yes	Yes	Yes	
136		110 W Miami								Unknown	Unknown	unknown	Single Family	Unknown	Unknown	Unknown	Unknown		Yes	Lead	Tier 1	Yes	Yes	Yes	
137		355 Laurel - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
138		111 W Miami - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
140		212 Cedar - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
141		211 Sycamore - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
142		211 Laurel - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
143		201 Laurel								Unknown	Unknown	ed to be original cons	Single Family	No	PVC	Unknown	Unknown		Yes	Lead	Tier 1	Yes	Yes	Yes	
144		202 W 2nd - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
145		201 W 2nd								Unknown	Unknown	ed to be original cons	Single Family	No	PVC	PVC	Unknown		Yes	Lead	Tier 1	Yes	Yes	Yes	
146		206 W 2nd - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
148		209 W 2nd								PEX	3/4"	2018	Single Family	No	PEX	PVC	After 2014		Yes	Lead	Tier 1	Yes	Yes	Yes	
149		201 Cedar								Copper	3/4"	unknown	Single Family	No	Copper	Copper	Between 1989 and 2014		Yes	Lead	Tier 1	Yes	Yes	Yes	
150		207 Cedar - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
151		210 W 1st - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
152		101 Cedar - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
154		209 W 1st - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
155		205 W 1st								Galvanized Steel	Unknown	unknown	Single Family	No	PVC	PVC	Before 1989		Yes	Lead	Tier 1	Yes	Yes	Yes	
156		201 W 1st - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
160		101 E 1st - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
161		102 E 1st								Unknown	Unknown	unknown	Single Family	Unknown	Unknown	Unknown	Unknown		Yes	Lead	Tier 1	Yes	Yes	Yes	
162		101 Laurel								PVC	Unknown	ed to be original cons	Single Family	No	PVC	Copper	Unknown		Yes	Lead	Tier 1	Yes	Yes	Yes	
163		105 E 2nd								Copper	1"	1990	Single Family	No	PEX	PEX	Between 1989 and 2014		Yes	Lead	Tier 1	Yes	Yes	Yes	
165		109 E 2nd - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
166		101 W 2nd - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
167		303 Laurel								PVC	Unknown	ed to be original cons	Single Family	Yes	PVC	PVC	Before 1989		Yes	Lead	Tier 1	Yes	Yes	Yes	
168		105 W Miami - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
169		311 Laurel - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
171		105 E Miami - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
172		109 E Miami								Galvanized Steel	3/4"	ed to be original cons	Single Family	No	PEX	PVC	After 2014		Yes	Lead	Tier 1	Yes	Yes	Yes	
174		203 E 4th - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
175		105 E 4th								Unknown	1"	unknown	Single Family	Unknown	Unknown	Unknown	Unknown		Yes	Lead	Tier 1	Yes	Yes	Yes	
176		361 Laurel - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
177		106 W 4th - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
178		401 Laurel - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
180		423 Main - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
181		415 Main - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
182		409 Main - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
184		402 Main - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
185		406 Main - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
187		418 Main - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
188		424 Main - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
189		500 Main - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
190		506 Main - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
192		205 E 6th								Unknown	Unknown	ed to be original cons	Other	No	PEX	Copper	Unknown		Yes	Lead	Tier 5	Yes	Yes	Yes	
193		602 Main								Unknown	Unknown	ed to be original cons	Other	No	PVC	PVC	Unknown		Yes	Lead	Tier 5	Yes	Yes	Yes	
194		622 Main - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
195		613 Main								Galvanized Steel	3/4"	ed to be original cons	Other	No	Copper	PVC	Before 1989		Yes	Lead	Tier 5	Yes	Yes	Yes	
196		700 Main - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
197		706 Main								PEX	1/2"	2020	Single Family	No	Copper	Galvanized Steel	Unknown		Yes	Lead	Tier 1	Yes	Yes	Yes	
198		711 Center - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
203		769 Center - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
210		811 Center								Galvanized Steel	3/4"	unknown	Single Family	Yes	PEX	PVC	After 2014		Yes	Lead	Tier 1	Yes	Yes	Yes	
212		407 E 9th								PVC	Unknown	ed to be original cons	Single Family	No	PVC	Unknown	Before 1989		Yes	Lead	Tier 1	Yes	Yes	Yes	
213		810 Center - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
218		804 Center - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
219		802 Center								Unknown	Unknown	unknown	Single Family	No	PVC	Unknown	Between 1989 and 2014		Yes	Lead	Tier 1	Yes	Yes	Yes	
221		762 Center								PVC	Unknown	unknown	Single Family	Unknown	Unknown	Unknown	Unknown		Yes	Lead	Tier 1	Yes	Yes	Yes	
222		760 Center								Copper	3/4"	ed to be original cons	Single Family	Yes	PVC	Copper	Before 1989		Yes	Lead	Tier 1	Yes	Yes	Yes	
223		400 E Broad								PVC	3/4"	ed to be original cons	Single Family	No	PVC	Copper	Before 1989		Yes	Lead	Tier 1	Yes	Yes	Yes	
224		712 Center								Copper	1/2"	unknown	Single Family	No	Galvanized Steel		Between 1989 and 2014		Yes	Lead	Tier 1	Yes	Yes	Yes	
227		705 Center - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
231		609 Center - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
232		604 Center - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
245		101 Palm								Unknown	Unknown	unknown	Multi-Family	No	PVC	Copper	Between 1989 and 2014		Yes	Lead	Tier 2	Yes	Yes	Yes	
246		211 E 2nd								PEX	1"	2018	Single Family	No	PEX	PVC	After 2014		Yes	Lead	Tier 1	Yes	Yes	Yes	
247		301 E 4th								PEX	1"	2014	Single Family	No	Copper	Copper	Unknown		Yes	Lead	Tier 1	Yes	Yes	Yes	
248		404 Center - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
252		359 Kansas								PVC	1/2"	1995	Single Family	Yes	PVC	PVC	Between 1989 and 2014		Yes	Lead	Tier 1	Yes	Yes	Yes	
253		309 E 4th - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
254		350 Kansas - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
257		409 E 5th								PVC	1"	1982	Single Family	No	PVC	Copper	Between 1989 and 2014		Yes	Lead	Tier 1	Yes	Yes	Yes	
259		506 E 5th - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
262		509 E 5th - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
263		601 E 5th								PVC	Unknown	1994	Single Family	No	PVC	PVC	Between 1989 and 2014		Yes	Lead	Tier 1	Yes	Yes	Yes	
264		504 Pine - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
265		608 E 5th								PEX	Unknown	ed to be original cons	Other	No	PEX	PVC	After 2014		Yes	Lead	Tier 5	Yes	Yes	Yes	
269		705 E 5th								Unknown	Unknown	ed to be original cons	Single Family	No	Copper	PVC	Unknown		Yes	Lead	Tier 1	Yes	Yes	Yes	
271		11155 Tucker Rd - Did not respond																	Yes	Lead	Tier 5	Yes	Yes	Yes	
274		705 E 6th								PVC	Unknown	ed to be original cons	Other	No	PEX	PEX	Between 1989 and 2014		Yes	Lead	Tier 5	Yes	Yes	Yes	
276		509 Magnolia								PEX	Unknown	ed to be original cons	Other	No	PEX	PEX	Between 1989 and 2014		Yes	Lead	Tier 5	Yes	Yes	Yes	

278	601 Holly	PVC	Unknown	id to be oriainal cons	Other		No	PVC	PEX	Between 1989 and 2014	Yes	Lead	Tier 5	Yes	Yes	Yes
279	601 Magnolia - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
280	601 E 6th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
282	509 Pine	PVC	3/4"	2011	Single Family		No	PEX	PVC	Between 1989 and 2014	Yes	Lead	Tier 1	Yes	Yes	Yes
286	510 Orange - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
292	502 E 7th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
293	506 E 7th	Unknown	Unknown	id to be oriainal cons	Single Family		No	PVC	Unknown	Unknown	Yes	Lead	Tier 1	Yes	Yes	Yes
294	505 E 7th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
295	508 E 7th	Galvanized Steel	1"	id to be oriainal cons	Single Family		No	PVC	Galvanized Steel	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
296	509 E 7th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
297	602 Pine - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
301	611 E 7th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
302	605 Holly - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
604	703 Holly #17	Copper	3/4"	id to be original cons	Single Family		Unknown	Copper	Copper Pipe with Lead Solder	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
305	708 E Holly #16	Copper	3/4"	id to be original cons	Single Family		Unknown	Copper	Copper Pipe with Lead Solder	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
306	706 E 7th #15	Copper	3/4"	id to be original cons	Single Family		Unknown	Copper	Copper Pipe with Lead Solder	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
307	704 E 7th #14	Copper	3/4"	id to be original cons	Single Family		Unknown	Copper	Copper Pipe with Lead Solder	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
308	704 Magnolia #12	Copper	3/4"	id to be original cons	Single Family		Unknown	Copper	Copper Pipe with Lead Solder	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
312	501 E Broad - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
314	601 E Broad #18	Copper	3/4"	id to be original cons	Single Family		Unknown	Copper	Copper Pipe with Lead Solder	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
315	605 E Broad - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
316	609 E Broad #19	Copper	3/4"	id to be original cons	Single Family		Unknown	Copper	Copper Pipe with Lead Solder	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
318	709 E Broad #20	Copper	3/4"	id to be original cons	Single Family		Unknown	Copper	Cooper Pipe with Lead Solder	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
319	752 Holly - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
321	802 Holly - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
322	755 Holly	Unknown	Unknown	id to be oriainal cons	Single Family		No	Unknown	Unknown	Unknown	Yes	Lead	Tier 1	Yes	Yes	Yes
328	751 Holly	Copper	3/4"	unknown	Other		No	PEX	PVC	Between 1989 and 2014	Yes	Lead	Tier 5	Yes	Yes	Yes
329	706 E Broad #30	Copper	3/4"	id to be original cons	Single Family		Unknown	Copper	Cooper Pipe with Lead Solder	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
330	704 E Broad #29	Copper	3/4"	id to be original cons	Single Family		Unknown	Copper	Cooper Pipe with Lead Solder	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
331	702 E Broad	Copper	3/4"	id to be original cons	Single Family		Unknown	Copper	Cooper Pipe with Lead Solder	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
332	610 E Broad #27	Copper	3/4"	id to be original cons	Single Family		Unknown	Copper	Cooper Pipe with Lead Solder	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
333	608 E Broad #26	Copper	3/4"	id to be original cons	Single Family		Unknown	Copper	Cooper Pipe with Lead Solder	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
334	606 E Broad #25	Copper	3/4"	id to be original cons	Single Family		Unknown	Copper	Cooper Pipe with Lead Solder	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
335	604 E Broad #24	Copper	3/4"	id to be original cons	Single Family		Unknown	Copper	Cooper Pipe with Lead Solder	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
336	752 Pine #23	Copper	3/4"	id to be original cons	Single Family		Unknown	Copper	Copper Pipe with Lead Solder	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
337	751 Pine #22	Copper	3/4"	id to be original cons	Single Family		Unknown	Copper	Copper Pipe with Lead Solder	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
338	506 E Broad #21	Copper	3/4"	id to be original cons	Single Family		Unknown	Copper	Copper Pipe with Lead Solder	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
340	505 E 8th	PEX	1"	2023	Single Family		No	PEX	PVC	After 2014	Yes	Lead	Tier 1	Yes	Yes	Yes
341	758 Pine #31	Copper	3/4"	id to be original cons	Single Family		Unknown	Copper	Copper Pipe with Lead Solder	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
342	603 E 8th #32	Copper	3/4"	id to be original cons	Single Family		Unknown	Copper	Copper Pipe with Lead Solder	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
343	605 E 8th #33	Copper	3/4"	id to be original cons	Single Family		Unknown	Copper	Copper Pipe with Lead Solder	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
344	607 E 8th #34	Copper	3/4"	id to be original cons	Single Family		Unknown	Copper	Copper Pipe with Lead Solder	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
345	609 E 8th #35	Copper	3/4"	id to be original cons	Single Family		Unknown	Copper	Copper Pipe with Lead Solder	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
346	758 Magnolia	Unknown	Unknown	id to be original cons	Single Family		No	Copper	Copper	Unknown	Yes	Lead	Tier 1	Yes	Yes	Yes
347	803 Holly	PEX	1"	1991	Single Family		No	PEX	Copper	Between 1989 and 2014	Yes	Lead	Tier 1	Yes	Yes	Yes
348	605 E 9th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
349	901 Magnolia	Unknown	Unknown	id to be original cons	Single Family		No	Unknown	Unknown	Between 1989 and 2014	Yes	Lead	Tier 1	Yes	Yes	Yes
350	606 E 9th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
351	602 E 9th	Galvanized Steel	3/4"	2020	Single Family		No	PVC	Unknown	After 2014	Yes	Lead	Tier 1	Yes	Yes	Yes
352	900 Center - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
353	902 Center - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
355	601 E 9th	PEX	1"	us property owner re	Single Family		No	PEX	PVC	After 2014	Yes	Lead	Tier 1	Yes	Yes	Yes
356	505 E 9th	Unknown	Unknown	unknown	Other		No	PVC	Copper	Between 1989 and 2014	Yes	Lead	Tier 5	Yes	Yes	Yes
358	803 Pine - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
360	710 E 9th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
361	902 Magnolia - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
362	1006 Holly	PVC	1/2"	1972	Single Family		No	PVC	Copper	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
363	1010 Holly	PVC	1"	2014	Single Family		Yes	PEX	Copper	After 2014	Yes	Lead	Tier 1	Yes	Yes	Yes
364	610 E 10th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
368	603 E 10th	Copper	1"	id to be original cons	Single Family		No	Copper	PVC	Unknown	Yes	Lead	Tier 1	Yes	Yes	Yes
371	907 Center - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
372	907 Center - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
376	308 W 10th #10	Copper	3/4"	id to be original cons	Single Family		Unknown	Copper	Copper Pipe with Lead Solder	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
377	1004 Walnut #11	Copper	3/4"	id to be original cons	Single Family		Unknown	Copper	Copper Pipe with Lead Solder	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
379	1001 Ash	PVC	4"	2017	Other		Unknown	Copper	PEX	After 2014	Yes	Lead	Tier 5	Yes	Yes	Yes
380	1001 Walnut	Galvanized Steel	Unknown	id to be original cons	Single Family		No	Galvanized Steel	Copper	Unknown	Yes	Lead	Tier 1	Yes	Yes	Yes
381	1205 Ash	PVC	4"	2017	Other		Unknown	Copper	Copper	After 2014	Yes	Lead	Tier 5	Yes	Yes	Yes
382	1009 Walnut - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
383	1205 Walnut	Unknown	Unknown	id to be original cons	Single Family		No	PVC	Unknown	Unknown	Yes	Lead	Tier 1	Yes	Yes	Yes
384-1	1207 Walnut - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
386	309 W 13th	Copper	2"	id to be original cons	Other		No	Copper	Copper	Before 1989	Yes	Lead	Tier 5	Yes	Yes	Yes
387	1303 Walnut	Unknown	Unknown	id to be original cons	Single Family		No	Unknown	Unknown	Unknown	Yes	Lead	Tier 1	Yes	Yes	Yes
388	1307 Walnut	PEX	3/4"	id to be oriainal cons	Single Family		No	PEX	PEX	Unknown	Yes	Lead	Tier 1	Yes	Yes	Yes
389-A5	1309 Walnut - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
390	311 W Park	Unknown	Unknown	id to be oriainal cons	Single Family		No	PVC	Copper	Unknown	Yes	Lead	Tier 1	Yes	Yes	Yes
391	1350 Walnut	Unknown	Unknown	id to be oriainal cons	Single Family		No	Unknown	Unknown	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
392	1351 Walnut - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
393	501 W 14th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
394	505 W 14th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
395	601 W 14th	Galvanized Steel	3/4"	id to be original cons	Single Family		Yes	Copper Pipe with Lead Solder	PEX	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
396	510 W Park	Unknown	Unknown	id to be original cons	Single Family		Unknown	Unknown	Unknown	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
397	506 W Park - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
398	500 W Park	PVC	1"	2014	Single Family		No	Copper Pipe with Lead Solder	Cooper Pipe with Lead Solder	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
399	715 W 17th	PEX	3/4"	id to be original cons	Single Family		No	Copper	PEX	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
400	701 W 14th	PVC	Unknown	id to be original cons	Single Family		No	PVC	Unknown	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
401	1401 Ash	Copper	Unknown	before 2004	Single Family		No	Copper	Unknown	Unknown	Yes	Lead	Tier 1	Yes	Yes	Yes
402	1405 Ash - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
403	504 W 14th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
404	506 W 14th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
405	505 W 15th	PVC	Unknown	id to be original cons	Other		No	PVC	Copper	Unknown	Yes	Lead	Tier 5	Yes	Yes	Yes
406	603 W 15th	Unknown	Unknown	id to be original cons	Single Family		No	Galvanized Steel	Copper	Between 1989 and 2014	Yes	Lead	Tier 1	Yes	Yes	Yes
407	602 W 14th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
408	605 W 15th	Copper	Unknown	id to be original cons	Single Family		No	Copper Pipe with Lead Solder	Copper Pipe with Lead Solder	Unknown	Yes	Lead	Tier 1	Yes	Yes	Yes
409	604 W 14th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
410	1406 Ash - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
411	1601 Ash - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
412	706 W 15th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
423	711 W 17th	Unknown	3/4"	id to be original cons	Single Family		No	PEX	PVC	Between 1989 and 2014	Yes	Lead	Tier 1	Yes	Yes	Yes
445	1301 Ash	Copper	1"	id to be original cons	Other		No	Copper	Copper	Unknown	Yes	Lead	Tier 5	Yes	Yes	Yes
446	306 W 13th	PVC	1"	id to be oriainal cons	Single Family		No	PEX		After 2014	Yes	Lead	Tier 1	Yes	Yes	Yes
447	304 W 13th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
448	300 W 13th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
449	210 W 13th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
453	1207 Sycamore	Unknown	Unknown	unknown	Single Family		No	Unknown	Unknown	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
454	201 W 13th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
455	1301 Sycamore - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
457	106 W 13th	PEX	1"	2020	Single Family		No	PEX	PVC	After 2014	Yes	Lead	Tier 1	Yes	Yes	Yes
458	107 W 13th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
459	1301 Laurel - Did not repond										Yes	Lead	Tier 5	Yes	Yes	Yes
460	105 W 13th	Copper	Unknown	id to be original cons	Single Family		No	PVC	Galvanized Steel	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
461	1311 Laurel - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
462	105 W Park - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
463	107 W Park	Galvanized Steel	Unknown	id to be original cons	Single Family		No	Copper	PVC	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
464	109 W Park	Galvanized Steel	Unknown	id to be original cons	Single Family		No	Unknown	PVC	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
465	111 W Park	PEX	1"	2010	Single Family		No	Copper	Galvanized Steel	Between 1989 and 2014	Yes	Lead	Tier 1	Yes	Yes	Yes
466	201 W Park	Unknown	Unknown	id to be original cons	Single Family		Yes	Unknown	PEX	Unknown	Yes	Lead	Tier 1	Yes	Yes	Yes
467	207 W Park	Copper	1/2"	id to be original cons	Single Family		No	Copper	Unknown	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
468	211 W Park	Galvanized Steel	Unknown	id to be original cons	Single Family		No	Unknown	Unknown	Unknown	Yes	Lead	Tier 1	Yes	Yes	Yes
469	301 W Park	PVC	1"	1985	Single Family		No	PVC	PEX	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
470	303 W Park - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
471	1351 Cedar	Copper	1/2"	id to be original cons	Single Family		Yes	Copper	PVC	Between 1989 and 2014	Yes	Lead	Tier 1	Yes	Yes	Yes
472	208 W Park - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
473	204 W Park - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
474	202 W Park	PEX	Unknown	2018	Single Family		No	Copper	Galvanized Steel	Unknown	Yes	Lead	Tier 1	Yes	Yes	Yes
475	110 W Park - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
476	106 W Park	PEX	1"	unknown	Single Family		No	Copper	PVC	Between 1989 and 2014	Yes	Lead	Tier 1	Yes	Yes	Yes
477	100 W Park	PVC	Unknown	nt property owner re	Multi-Family		No	PVC	Unknown	Between 1989 and 2014	Yes	Lead	Tier 2	Yes	Yes	Yes
478	1359 Laurel - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
479	105 W 14th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
481	107 W 14th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
482	110 W 14th	PEX	Unknown	unknown	Single Family		No	PEX	Copper	Unknown	Yes	Lead	Tier 1	Yes	Yes	Yes
484	1359 Sycamore - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
485	205 W 14th	Unknown	Unknown	id to be original cons	Single Family		No	Unknown	Unknown	Unknown	Yes	Lead	Tier 1	Yes	Yes	Yes
486	1360 Cedar - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
487	1361 Cedar - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
488	305 W 14th	Unknown	Unknown	id to be original cons	Single Family		No	Unknown	Unknown	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
489	309 W 14th	PVC	1"	1994	Single Family		Yes	PVC	PVC	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
490	1402 Ash	Copper	3/4"	id to be original cons	Single Family		No	PVC	Copper	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
491	308 W Christel Lane	Unknown	Unknown	id to be original cons	Single Family		Unknown	Unknown	Unknown	Between 1989 and 2014	Yes	Lead	Tier 1	Yes	Yes	Yes
495	1406 Sycamore - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
496	1501 Laurel	PVC	1"	id to be original cons	Single Family		Yes	Copper	Copper	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
498	1407 Laurel	Copper	3/4"	id to be original cons	Single Family		No	PEX	Copper	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
499	1406 Laurel - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
502	205 W 17th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
503	1701 Laurel	Unknown	Unknown	id to be original cons	Other		Unknown	Copper	Unknown	Before 1989	Yes	Lead	Tier 5	Yes	Yes	Yes
504	1801 Laurel - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
505	1805 Laurel	Copper	3/4"	revious owner replac	Single Family		No	Copper	Copper	Unknown	Yes	Lead	Tier 1	Yes	Yes	Yes
506	1901 Laurel - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
507	9714 Thomas Rd	Unknown	Unknown	id to be original cons	Single Family		No	PVC	Unknown	Unknown	Yes	Lead	Tier 1	Yes	Yes	Yes
508	21138 E 975th	Unknown	Unknown	id to be original cons	Single Family		No	Unknown	Unknown	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
510	21192 E 975th	Unknown	Unknown	id to be original cons	Single Family		No	PVC	Unknown	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
511	9807 Tipton Rd - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
512	21181 E 975th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
513	9735 Tipton Rd	Copper	1"	id to be original cons	Single Family		No	Copper	PVC	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
514	21155 E 975th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes
515	1710 Laurel	Copper	1"	id to be original cons	Other		Unknown	Copper	PEX	Before 1989	Yes	Lead	Tier 5	Yes	Yes	Yes
517	108 E 15th	Unknown	Unknown	id to be original cons	Single Family		No	PVC	Unknown	Unknown	Yes	Lead	Tier 1	Yes	Yes	Yes
518	1504 Maple	Unknown	Unknown	id to be original cons	Single Family		No	Unknown	Unknown	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
519	110 E 14th	Unknown	Unknown	id to be original cons	Single Family		No	Copper	Galvanized Steel	Unknown	Yes	Lead	Tier 1	Yes	Yes	Yes
520	201 E 15th	Copper	1"	1960	Single Family		No	Copper	Copper	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes

521	1404 Maple - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
522	1402 Maple	Copper	1/2"	id to be original cons	Single Family	No	Copper	PVC	Unknown		Yes	Lead	Tier 1	Yes	Yes	Yes		
523	206 E 14th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
524	209 E 15th	Galvanized Steel	1"	id to be original cons	Single Family	Yes	Copper	Copper	Before 1989		Yes	Lead	Tier 1	Yes	Yes	Yes		
525	208 E 14th	Unknown	3/4"	us property owner n	Single Family	Yes	PVC	Unknown	Before 1989		Yes	Lead	Tier 1	Yes	Yes	Yes		
526	300 E 14th	Galvanized Steel	3/4"	id to be original cons	Single Family	No	PEX	PVC	Before 1989		Yes	Lead	Tier 1	Yes	Yes	Yes		
527	301 E 15th	PVC	3/4"	2015	Single Family	No	PVC	PVC	Between 1989 and 2014		Yes	Lead	Tier 1	Yes	Yes	Yes		
528	310 E 15th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
529	1609 Locust	Unknown	Unknown	id to be original cons	Single Family	No	PEX	PEX	Unknown		Yes	Lead	Tier 1	Yes	Yes	Yes		
530	1709 Locust	PEX	3/4"	2023	Single Family	No	PVC	PEX	Between 1989 and 2014		Yes	Lead	Tier 1	Yes	Yes	Yes		
533	1710 Locust	Unknown	Unknown	unknown		No	Copper	Unknown	Before 1989		Yes	Lead	Tier 5	Yes	Yes	Yes		
534	1408 Locust - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
535-A3	1404 Locust - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
537	404 E 14th	Unknown	Unknown	id to be original cons	Single Family	Yes	PEX	PEX	Between 1989 and 2014		Yes	Lead	Tier 1	Yes	Yes	Yes		
538	311 E 14th	Unknown	Unknown	1971	Single Family	Unknown	PVC	PVC	Before 1989		Yes	Lead	Tier 1	Yes	Yes	Yes		
539	307 E 14th	PVC	Unknown	id to be original cons	Single Family	No	PVC	Galvanized Steel	Before 1989		Yes	Lead	Tier 1	Yes	Yes	Yes		
541	401 E 14th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
543	1356 Locust - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
544	402 E Park - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
545	404 E Park	Unknown	Unknown	unknown	Single Family	No	Unknown	Unknown	Unknown		Yes	Lead	Tier 1	Yes	Yes	Yes		
556	410 E 14th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
563	500 E Park - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
564	504 E Park	Unknown	Unknown	id to be original cons	Single Family	No	Unknown	Unknown	Unknown		Yes	Lead	Tier 1	Yes	Yes	Yes		
566	604 E Park	Unknown	1"	1975	Single Family	No	PVC	PVC	Unknown		Yes	Lead	Tier 1	Yes	Yes	Yes		
567	610 E Park - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
568	700 E Park - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
569	701 E 14th	Unknown	Unknown	id to be original cons	Other	Unknown	PVC	PEX	Before 1989		Yes	Lead	Tier 5	Yes	Yes	Yes		
570	1357 Magnolia - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
571	700 E 14th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
572	1701 Holly	PEX	1/2"	2014	Single Family	No	PEX	PVC	After 2014		Yes	Lead	Tier 1	Yes	Yes	Yes		
573	21569 E 1000 Rd	PVC	1"	id to be original cons	Single Family	No	Copper	Copper	Before 1989		Yes	Lead	Tier 1	Yes	Yes	Yes		
575	1310 Holly - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
576	1300 Holly	Unknown	Unknown	1996	Single Family	Yes	PVC	PEX	Between 1989 and 2014		Yes	Lead	Tier 1	Yes	Yes	Yes		
577	705 E Park	Galvanized Steel	1"	id to be original cons	Single Family	No	Copper	PVC	Before 1989		Yes	Lead	Tier 1	Yes	Yes	Yes		
578	601 E Park	Galvanized Steel	3/4"	id to be original cons	Single Family	No	Copper	PVC	Between 1989 and 2014		Yes	Lead	Tier 1	Yes	Yes	Yes		
583	307 E Park	PVC	Unknown	1974	Other	No	PVC	PVC	Before 1989		Yes	Lead	Tier 5	Yes	Yes	Yes		
584	301 E Park	Copper	3/4"	id to be original cons	Single Family	No	Copper	Copper	Before 1989		Yes	Lead	Tier 1	Yes	Yes	Yes		
585	211 E Park - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
586	209 E Park - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
587	207 E Park - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
588	205 E Park - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
589	1308 Maple - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
590	109 E Park	Unknown	3/4"	id to be original cons	Single Family	Unknown	Unknown	Unknown	Before 1989		Yes	Lead	Tier 1	Yes	Yes	Yes		
591	105 E Park	Unknown	Unknown	id to be original cons	Single Family	Yes	Unknown	Unknown	Before 1989		Yes	Lead	Tier 1	Yes	Yes	Yes		
592	1310 Laurel	Copper	3/4"	id to be original cons	Other	No	PVC	Copper	Before 1989		Yes	Lead	Tier 5	Yes	Yes	Yes		
593	1356 Laurel	Copper	3/4"	id to be original cons	Other	No	Copper	PVC	Between 1989 and 2014		Yes	Lead	Tier 5	Yes	Yes	Yes		
594	104 E Park	Copper	3/4"	2001	Single Family	No	Copper	PVC	Between 1989 and 2014		Yes	Lead	Tier 1	Yes	Yes	Yes		
595	108 E Park - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
597	1356 Maple - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
598	203 E 14th	Unknown	Unknown	id to be original cons	Single Family	No	Unknown	Unknown	Unknown		Yes	Lead	Tier 1	Yes	Yes	Yes		
599	200 E Park	Unknown	Unknown	id to be original cons	Single Family	No	Unknown	Unknown	Before 1989		Yes	Lead	Tier 1	Yes	Yes	Yes		
600	206 E Park	Unknown	1"	unknown	Single Family	No	Copper	PVC	Unknown		Yes	Lead	Tier 1	Yes	Yes	Yes		
601	205 E 14th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
602	210 E Park	Galvanized Steel	Unknown	id to be original cons	Single Family	No	Unknown	Unknown	Before 1989		Yes	Lead	Tier 1	Yes	Yes	Yes		
603	1359 Palm										Yes	Lead	Tier 5	Yes	Yes	Yes		
604	1360 Palm	PVC	1"	unknown	Single Family	Yes	PEX	PEX	After 2014		Yes	Lead	Tier 1	Yes	Yes	Yes		
605	300 E Park - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
606	306 E Park - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
607	310 E Park	Copper	3/4"	id to be original cons	Single Family	No	Copper	Copper	Unknown		Yes	Lead	Tier 1	Yes	Yes	Yes		
608	1309 Prospect	Unknown	Unknown	id to be original cons	Single Family	No	Unknown	Unknown	Before 1989		Yes	Lead	Tier 1	Yes	Yes	Yes		
609	1305 Prospect - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
610	1301 Prospect	Unknown	3/4"	id to be original cons	Single Family	No	Unknown	Unknown	Before 1989		Yes	Lead	Tier 1	Yes	Yes	Yes		
611	305 E 13th										Yes	Lead	Tier 5	Yes	Yes	Yes		
612	303 E 13th	Unknown	Unknown	unknown	Single Family	No	Unknown	Unknown	Before 1989		Yes	Lead	Tier 1	Yes	Yes	Yes		
613	1207 Palm - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
614	205 E 13th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
615	203 E 13th	Unknown	Unknown	unknown	Single Family	Unknown	Unknown	Unknown	Unknown		Yes	Lead	Tier 1	Yes	Yes	Yes		
616	201 E 13th	Copper	Unknown	id to be original cons	Other	No	PVC	PEX	After 2014		Yes	Lead	Tier 5	Yes	Yes	Yes		
617	202 E 12th	PVC	3/4"	id to be original cons	Single Family	No	PVC	Other Non Lead	Unknown		Yes	Lead	Tier 1	Yes	Yes	Yes		
618	102 E 12th	Copper	Unknown	id to be original cons	Other	No	PEX	Copper	Unknown		Yes	Lead	Tier 5	Yes	Yes	Yes		
619	106 E 12th	Copper	1"	id to be original cons	Single Family	Yes	PEX	Copper	Unknown		Yes	Lead	Tier 1	Yes	Yes	Yes		
623	100 E 13th	Copper	3/4"	id to be original cons	Single Family	No	Copper	Copper	Before 1989		Yes	Lead	Tier 1	Yes	Yes	Yes		
626	109 E 13th	Copper	1"	1990	Single Family	No	Copper	Copper	Between 1989 and 2014		Yes	Lead	Tier 1	Yes	Yes	Yes		
627	106 E 13th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
629	206 E 13th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
630	208 E 13th	Unknown	Unknown	unknown	Single Family	No	Unknown	Unknown	Unknown		Yes	Lead	Tier 1	Yes	Yes	Yes		
632	1207 Locust	PVC	Unknown	id to be original cons	Single Family	Yes	PVC	Copper	Before 1989		Yes	Lead	Tier 1	Yes	Yes	Yes		
633	401 E 13th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
635	405 E 13th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
636	1300 High - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
637	1302 High - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
638	1304 High - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
638A	1306 High	Unknown	Unknown	id to be original cons	Single Family	Yes	Unknown	Unknown	Unknown		Yes	Lead	Tier 1	Yes	Yes	Yes		
640	1302 Orange	PVC	1"	id to be original cons	Single Family	Yes	PEX	PEX	Before 1989		Yes	Lead	Tier 1	Yes	Yes	Yes		
641	501 E 13th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
642	1206 Orange	PEX	1"	2021	Single Family	No	PEX	PEX	Before 1989		Yes	Lead	Tier 1	Yes	Yes	Yes		
643	1202 Orange	PVC	1"	2008	Single Family	No	PVC	Copper	Between 1989 and 2014		Yes	Lead	Tier 1	Yes	Yes	Yes		
645	404 E 12th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
646	402 E 12th	PEX	3/4"	2021	Single Family	No	Copper	Copper	Before 1989		Yes	Lead	Tier 1	Yes	Yes	Yes		
647	400 E 12th	PVC	Unknown	1979	Single Family	No	PVC	Unknown	Before 1989		Yes	Lead	Tier 1	Yes	Yes	Yes		
648	1203 Locust - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
649	310 E 12th	PVC	Unknown	unknown	Single Family	Yes	PVC	Copper	Between 1989 and 2014		Yes	Lead	Tier 1	Yes	Yes	Yes		
650	308 E 12th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
651	306 E 12th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
654	1201 Palm	PVC	3/4"	unknown	Single Family	No	PVC	Copper	Unknown		Yes	Lead	Tier 1	Yes	Yes	Yes		
656	205 E 12th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
659	305 E 12th	Unknown	Unknown	id to be original cons	Single Family	No	Unknown	Unknown	Unknown		Yes	Lead	Tier 1	Yes	Yes	Yes		
661	309 E 12th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
662	902 Palm - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
663	303 E 10th	Galvanized Steel	3/4"	id to be original cons	Single Family	No	Galvanized Steel	PEX	Unknown		Yes	Lead	Tier 1	Yes	Yes	Yes		
664	905 Palm #1A	Copper	3/4"	id to be original construction		Unknown	Copper	Copper Pipe with Lead Solder	Before 1989		Yes	Lead	Tier 5	Yes	Yes	Yes		
665	907 Palm #1B	Copper	3/4"	id to be original construction		Unknown	Copper	Copper Pipe with Lead Solder	Before 1989		Yes	Lead	Tier 5	Yes	Yes	Yes		
666	909 Palm #2A	Copper	3/4"	id to be original construction		Unknown	Copper	Copper Pipe with Lead Solder	Before 1989		Yes	Lead	Tier 5	Yes	Yes	Yes		
667	911 Palm #2B	Copper	3/4"	id to be original construction		Unknown	Copper	Copper Pipe with Lead Solder	Before 1989		Yes	Lead	Tier 5	Yes	Yes	Yes		
668	209 E 10th	Copper	3/4"	id to be original cons	Other	Unknown	Copper	Copper Pipe with Lead Solder	Between 1989 and 2014		Yes	Lead	Tier 5	Yes	Yes	Yes		
669	207 E 10th	Unknown	Unknown	id to be original cons	Single Family	No	Unknown	Unknown	Unknown		Yes	Lead	Tier 1	Yes	Yes	Yes		
670	201 E 10th	PVC	3/4"	id to be original cons	Single Family	Unknown	PVC	PVC	Between 1989 and 2014		Yes	Lead	Tier 1	Yes	Yes	Yes		
671	109 E 10th	PEX	3/4"	us property owner n	Single Family	No	PVC	PVC	After 2014		Yes	Lead	Tier 1	Yes	Yes	Yes		
673	101 E 10th	PVC	1"	1997	Single Family	No	PVC	Unknown	Between 1989 and 2014		Yes	Lead	Tier 1	Yes	Yes	Yes		
675	107 W 10th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
678	903 Sycamore	Copper	3/4"	id to be original cons	Single Family	Unknown	Copper	Copper Pipe with Lead Solder	Before 1989		Yes	Lead	Tier 1	Yes	Yes	Yes		
679	204 W 9th #B	Copper	3/4"	id to be original cons	Single Family	Unknown	Copper	Copper Pipe with Lead Solder	Before 1989		Yes	Lead	Tier 1	Yes	Yes	Yes		
680	206 W 9th #9	Copper	3/4"	id to be original cons	Single Family	Unknown	Copper	Copper Pipe with Lead Solder	Before 1989		Yes	Lead	Tier 1	Yes	Yes	Yes		
681	900 Cedar	Galvanized Steel	1"	2006	Single Family	No	PVC	Copper	Before 1989		Yes	Lead	Tier 1	Yes	Yes	Yes		
682	906 Cedar	PVC	1"	id to be original cons	Single Family	No	PEX	PEX	Between 1989 and 2014		Yes	Lead	Tier 1	Yes	Yes	Yes		
683	806 Cedar	Unknown	Unknown	id to be original cons	Single Family	No	PVC	Copper	Before 1989		Yes	Lead	Tier 1	Yes	Yes	Yes		
685	20694 E 1050th Rd	Galvanized Steel	3/4"	id to be original cons	Single Family	No	Galvanized Steel	Copper	Before 1989		Yes	Lead	Tier 1	Yes	Yes	Yes		
689	1001 Sycamore - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
690	108 W 10th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
691	104 W 10th	Galvanized Steel	3/4"	id to be original cons	Single Family	No	Copper	Galvanized Steel	Unknown		Yes	Lead	Tier 1	Yes	Yes	Yes		
692	1001 Laurel - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
693	1005 Laurel - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
695	1011 Laurel	Unknown	Unknown	id to be original cons	Single Family	No	Unknown	Unknown	Unknown		Yes	Lead	Tier 1	Yes	Yes	Yes		
696	1012 Laurel	Unknown	Unknown	id to be original cons	Other	No	PVC	PEX	Before 1989		Yes	Lead	Tier 5	Yes	Yes	Yes		
697	100 E 10th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
698	104 E 10th	PVC	Unknown	us property owner n	Single Family	No	PVC	Copper	Unknown		Yes	Lead	Tier 1	Yes	Yes	Yes		
699	108 E 10th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
700	1007 Maple	Unknown	Unknown	id to be original cons	Single Family	No	Galvanized Steel	Unknown	Before 1989		Yes	Lead	Tier 1	Yes	Yes	Yes		
701	201 E 12th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
702	200 E 10th	Unknown	Unknown	id to be original cons	Single Family	No	PEX	PEX	Unknown		Yes	Lead	Tier 1	Yes	Yes	Yes		
704	204 E 10th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
707	1006 Palm #6A	Copper	3/4"	id to be original construction		No	Copper	Copper Pipe with Lead Solder	Before 1989		Yes	Lead	Tier 5	Yes	Yes	Yes		
708	1004 Palm #6B	Copper	3/4"	id to be original construction		No	Copper	Copper Pipe with Lead Solder	Before 1989		Yes	Lead	Tier 5	Yes	Yes	Yes		
709-A3	300 E 10th #3B	Copper	3/4"	id to be original construction		No	Copper	Copper Pipe with Lead Solder	Before 1989		Yes	Lead	Tier 5	Yes	Yes	Yes		
710-A5	302 E 10th #3A	Copper	3/4"	id to be original construction		No	Copper	Copper Pipe with Lead Solder	Before 1989		Yes	Lead	Tier 5	Yes	Yes	Yes		
711	306 E 10th #4A	Copper	3/4"	id to be original construction		No	Copper	Copper Pipe with Lead Solder	Before 1989		Yes	Lead	Tier 5	Yes	Yes	Yes		
712	304 E 10th #4B	Copper	3/4"	id to be original construction		No	Copper	Copper Pipe with Lead Solder	Before 1989		Yes	Lead	Tier 5	Yes	Yes	Yes		
713	1003 Linn #5A	Copper	3/4"	id to be original construction		No	Copper	Copper Pipe with Lead Solder	Before 1989		Yes	Lead	Tier 5	Yes	Yes	Yes		
714	1005 Linn #5B	Copper	3/4"	id to be original construction		No	Copper	Copper Pipe with Lead Solder	Before 1989		Yes	Lead	Tier 5	Yes	Yes	Yes		
715	901 Palm - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
716	206 E 9th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
717	202 E 9th	Unknown	Unknown	id to be original cons	Single Family	No	Unknown	Unknown	Unknown		Yes	Lead	Tier 1	Yes	Yes	Yes		
718	108 E 9th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
719	106 E 9th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
720	102 E 9th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
721	104 E 8th	Unknown	Unknown	id to be original cons	Single Family	No	Copper	PEX	After 2014		Yes	Lead	Tier 1	Yes	Yes	Yes		
722	104 W 8th	Copper	1"	id to be original cons	Single Family	No	Copper	Unknown	Unknown		Yes	Lead	Tier 1	Yes	Yes	Yes		
723	805 Laurel	Copper	3/4"	id to be original cons	Single Family	Yes	Copper	Copper	Before 1989		Yes	Lead	Tier 1	Yes	Yes	Yes		
725	806 Maple - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
726	205 E 9th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
727	209 E 9th	Copper	Unknown	id to be original cons	Other	No	PVC	PEX	Unknown		Yes	Lead	Tier 5	Yes	Yes	Yes		
728	211 E 9th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
730	206 E 8th	PVC	3/4"	id to be original cons	Single Family	No	Copper	PVC	Between 1989 and 2014		Yes	Lead	Tier 1	Yes	Yes	Yes		
731	202 E 8th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
732	803 Maple - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
733	759 Maple	Galvanized Steel	Unknown	1996	Single Family	No	Copper	PVC	Between 1989 and 2014		Yes	Lead	Tier 1	Yes	Yes	Yes		
734	201 E 8th	Copper	3/4"	2015	Single Family	No	Copper	PVC	Between 1989 and 2014		Yes	Lead	Tier 1	Yes	Yes	Yes		
735	203 E 8th - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
738	751 Linn - Did not respond										Yes	Lead	Tier 5	Yes	Yes	Yes		
739	753 Linn	PVC	1/2"	id to be original cons	Single Family	No	Copper	PVC	After 2014		Yes	Lead	Tier 1	Yes	Yes	Yes		

741	759 Linn	Copper	3/4"	1977	Single Family	No	Copper	Galvanized Steel	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
743	809 Sycamore - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
744	801 Sycamore - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
746	205 W 8th	Copper	Unknown	id to be original cons	Single Family	No	Copper Pipe with Lead Solder	PVC	Unknown	Yes	Lead	Tier 1	Yes	Yes	Yes
747	758 Cedar	Copper	1"	id to be original cons	Single Family	No	Copper	PVC	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
748A	759 Cedar	PEX	3/4"	2019	Single Family	No	Copper	Copper	Unknown	Yes	Lead	Tier 1	Yes	Yes	Yes
749	751 Cedar - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
751	753 Sycamore	PEX	3/4"	as property owner n	Single Family	No	PVC	Copper	Unknown	Yes	Lead	Tier 1	Yes	Yes	Yes
753	201 W 8th - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
756	105 W Broad - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
757	101 W Broad - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
758	101 E Broad - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
759	105 E Broad - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
760	109 E Broad	Unknown	1"	id to be original cons	Single Family	No	Copper	PVC	Unknown	Yes	Lead	Tier 1	Yes	Yes	Yes
761	111 E Broad - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
762	705 Maple - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
763	205 E Broad - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
764	305 E Broad	Copper	1/2"	unknown	Single Family	No	PVC	Unknown	After 2014	Yes	Lead	Tier 1	Yes	Yes	Yes
765	713 Main	Galvanized Steel	3/4"	id to be original cons	Single Family	No	Copper	Copper	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
766	754 Maple	Unknown	Unknown	id to be original cons	Single Family	No	Copper	PEX	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
767	755 Maple - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
768	106 E Broad - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
769	100 W Broad - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
770	106 W Broad - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
771	110 W Broad	Unknown	Unknown	id to be original cons	Single Family	Yes	Unknown	Unknown	Unknown	Yes	Lead	Tier 1	Yes	Yes	Yes
772	708 Cedar	Unknown	Unknown	nt property owner re	Multi-Family	Unknown	Unknown	Unknown	Unknown	Yes	Lead	Tier 2	Yes	Yes	Yes
773	707 Cedar	Unknown	Unknown	id to be original cons	Single Family	No	Copper	Unknown	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
775	703 Cedar - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
776	207 W 7th	PVC	1"	2004	Single Family	Yes	PVC	PVC	Between 1989 and 2014	Yes	Lead	Tier 1	Yes	Yes	Yes
778	201 W 7th	PVC	1"	1992	Single Family	Yes	Copper	Copper	Between 1989 and 2014	Yes	Lead	Tier 1	Yes	Yes	Yes
779	111 W 7th - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
780	109 W 7th - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
781	105 W 7th - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
782	101 W 7th	Unknown	1/2"	unknown	Single Family	No	PVC	Copper	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
783	103 E 7th	PVC	Unknown	id to be original cons	Other	No	PVC	PEX	Before 1989	Yes	Lead	Tier 5	Yes	Yes	Yes
785	108 E 7th - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
786	104 E 7th	Copper	3/4"	id to be original cons	Single Family	No	PVC		Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
787	100 E 7th	Unknown	Unknown	id to be original cons	Single Family	Unknown	PVC	PVC	Unknown	Yes	Lead	Tier 1	Yes	Yes	Yes
788	102 W 7th	PEX	1"	1970	Single Family	No	PEX		Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
789	106 W 7th	Unknown	Unknown	id to be original cons	Single Family	Unknown	Unknown	Unknown	Unknown	Yes	Lead	Tier 1	Yes	Yes	Yes
790	110 W 7th - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
792	206 W 7th - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
793	210 W 7th	Unknown	Unknown	id to be original cons	Single Family	Yes	Unknown	PVC	Unknown	Yes	Lead	Tier 1	Yes	Yes	Yes
794	701 W 15th - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
795	405 Cedar	Unknown	Unknown	id to be original cons	Single Family	No	Unknown	Unknown	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
799	21156 E 975th - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
802	1704 Laurel - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
804	20746 E 1100 Rd - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
806	1201 Ash - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
808	1210 Holly	Copper	3/4"	id to be original cons	Single Family	Yes	Copper	PEX	Between 1989 and 2014	Yes	Lead	Tier 1	Yes	Yes	Yes
810	401 W Miami - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
813	605 E 5th - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
814	9th & RR tracks - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
815	401 W Floyd Johnson Lane	PEX	3/4"	2020	Single Family	No	PEX	PEX	After 2014	Yes	Lead	Tier 1	Yes	Yes	Yes
816	305 W Floyd Johnson Drive	PVC	Unknown	1994	Single Family	No	PVC	Unknown	Between 1989 and 2014	Yes	Lead	Tier 1	Yes	Yes	Yes
817	804 Magnolia - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
820	1002 Magnolia - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
821	305 W 17th - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
822	620 Dogwood Lane	PVC	1"	id to be original cons	Single Family	No	PEX	Unknown	Between 1989 and 2014	Yes	Lead	Tier 1	Yes	Yes	Yes
823	9453 Trump	Copper	1"	id to be original cons	Other	No	Copper	PVC	Between 1989 and 2014	Yes	Lead	Tier 5	Yes	Yes	Yes
825	752 Cedar	PVC	1"	1997	Single Family	No	PVC	PEX	Before 1989	Yes	Lead	Tier 1	Yes	Yes	Yes
826	1609 Laurel	PVC	2"	id to be original cons	Other	Yes	PVC	PEX	Between 1989 and 2014	Yes	Lead	Tier 5	Yes	Yes	Yes
828	21195 E 975th	PVC	Unknown	id to be original cons	Single Family	No	PVC	Unknown	Between 1989 and 2014	Yes	Lead	Tier 1	Yes	Yes	Yes
830	300 W 14th - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
831	21157 E 975th	Copper	Unknown	id to be original cons	Single Family	Unknown	Copper	PEX	Between 1989 and 2014	Yes	Lead	Tier 1	Yes	Yes	Yes
833	1404 Ash	Unknown	Unknown	id to be original cons	Single Family	No	Unknown	Unknown	Between 1989 and 2014	Yes	Lead	Tier 1	Yes	Yes	Yes
838	Quanset Hut	PVC	1"	id to be original cons	Other	No	PVC	PVC	Between 1989 and 2014	Yes	Lead	Tier 5	Yes	Yes	Yes
840	903 Holly - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
841	311 W 6th	Unknown	Unknown	id to be original cons	Single Family	No	PVC	Unknown	Between 1989 and 2014	Yes	Lead	Tier 1	Yes	Yes	Yes
842	206 W 5th	Unknown	Unknown	id to be original cons	Single Family	No	Unknown	Unknown	Unknown	Yes	Lead	Tier 1	Yes	Yes	Yes
844	773 Main - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
845	506 E 5th - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
846	903 Magnolia - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
847	1508 Ash - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
848	21108 E 975th	Copper	1/2"	assumed to be oriain	Single Family	Yes	Copper	Copper	Between 1989 and 2014	Yes	Lead	Tier 1	Yes	Yes	Yes
849	610 E 9th - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
850	608 E 8th	Unknown	3/4"	id to be original cons	Single Family	No	PVC	PEX	Between 1989 and 2014	Yes	Lead	Tier 1	Yes	Yes	Yes
851	21109 E 975th	Copper	3/4"	id to be original cons	Single Family	No	PVC	PVC	After 2014	Yes	Lead	Tier 1	Yes	Yes	Yes
852	21123 E 975th - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
853	1500 Ash - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
854	1204 Sycamore - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
855	420 W 4th	PVC	3/4"	id to be original cons	Single Family	No	PEX	Copper	Between 1989 and 2014	Yes	Lead	Tier 1	Yes	Yes	Yes
856	801 Magnolia - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
858	705 W 15th - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
860	192 Palm - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
861	9421 Thomas Rd	PVC	4"	2004	Other	Yes	PVC	PEX	Between 1989 and 2014	Yes	Lead	Tier 5	Yes	Yes	Yes
862	707 W 15th - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
863	21124 E 975th	PVC	Unknown	2009	Single Family	No	PEX	PEX	Between 1989 and 2014	Yes	Lead	Tier 1	Yes	Yes	Yes
864	600 W 15th West Side NW	PVC	1/2"	1981	Multi-Family	No	PEX	PVC	Before 1989	Yes	Lead	Tier 2	Yes	Yes	Yes
865	600 W 15th East Side NE	PVC	1/2"	1981	Multi-Family	No	PEX	PVC	Before 1989	Yes	Lead	Tier 2	Yes	Yes	Yes
866	1356 Ash - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
867	205 E 18th - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
868	105 E 7th	Copper	3/4"	id to be original cons	Other	No	PVC	PEX	Between 1989 and 2014	Yes	Lead	Tier 5	Yes	Yes	Yes
869	702 Laurel - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
870	1006 Sycamore	PEX	3/4"	unknown	Single Family	Yes	PEX	Copper	Between 1989 and 2014	Yes	Lead	Tier 1	Yes	Yes	Yes
871	11240 Tucker Rd	PVC	3/4"	2014	Other	No	PEX	Unknown	Unknown	Yes	Lead	Tier 5	Yes	Yes	Yes
872	22380 E 1000 Rd #5 - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
873	11169 Tucker Rd - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
874	21659 E 1100 Rd - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
875	21659 E 1100 Rd - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
877	106 W Miami - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
878	207 W 17th	PEX	1"	id to be original cons	Single Family	Yes	PEX	PEX	After 2014	Yes	Lead	Tier 1	Yes	Yes	Yes
879	427 Cobra Drive	Unknown	Unknown	id to be original cons	Other	No	Unknown	Unknown	After 2014	Yes	Lead	Tier 5	Yes	Yes	Yes
880	11231 Tucker Rd - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
881	22380 E 1000 Rd	PEX	Unknown	id to be original cons	Other	No	PEX	PVC	Unknown	Yes	Lead	Tier 5	Yes	Yes	Yes
883	808 Holly - Did not respond									Yes	Lead	Tier 5	Yes	Yes	Yes
										Yes	Lead	Tier 5	Yes	Yes	Yes
										Yes	Lead	Tier 5	Yes	Yes	Yes
										Yes	Lead	Tier 5	Yes	Yes	Yes
										Yes	Lead	Tier 5	Yes	Yes	Yes
										Yes	Lead	Tier 5	Yes	Yes	Yes
164	210 Laurel	PVC	Unknown	1988	Single Family	No	PVC	Copper	Between 1989 and 2014	Yes	Lead	Tier 1	Yes	Yes	Yes
										Yes	Lead	Tier 5

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes

Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes
Yes	Lead	Tier 5	Yes	Yes	Yes